



48 x 96

SPECIFICATIONS

DISPLAY

4-digit (7 segment LED) 0.5" height Display Messages:

- “Or” - a) Appears when measurement exceeds display scaling range(9999) for signal inputs
- b) When open sensor is detected. (Applicable for TC/RTD/-5 to 56mV)
- “rE” a) Appears when measurement is below display scaling range (-1999) for signal inputs.
- B) Sensor reverse condition occurs. (Applicable for TC/RTD/mV)

Display alternating between PV and ALrM with LED of respective alarm flashing.

(Programmable annunciator option)

LED Status Annunciators - Alarm ON (2 nos)

POWER

85 to 270V AC/DC (AC : 50 or 60Hz),
5VA (Optional) - 24V DC

SETTINGS

Via three keys on front panel.

MEMORY

Nonvolatile EEPROM retains all programmable parameters and values.

MAIN SENSOR INPUT (Universal)

Thermocouple inputs

- J : -200 to 750°C
- K : -200 to 1350°C
- T : -200 to 400°C
- R : 0 to 1750°C
- S : 0 to 1750°C

RTD input (2 wire or 3 wire)

PT100 : -100 to 850°C

Signal inputs

- mV (linear) : - 5 to 56mV
- Voltage : 0 - 10V DC
- Current : 0 - 20mA DC

INSTALLATION ACCURACY

- Temperature : 0.25% of Span ±1°C (20min.Warmup)
- Signal input : 0.05% ±1 digit

ALARM OUTPUTS

- 2 nos : Relay output : 5A @ 250V AC or 24V DC
- Alarm modes - Alarm High, Alarm Low, Band, Fault output and Fault diagnosis.
- Hysteresis - Programmable.
- Annunciator - Programmable.
- Reset Action - Programmable : automatic or latched.
- Standby Mode - Programmable : enable or disable.

SENSOR SUPPLY

24V DC supply to power the sensor

LINEAR DC OUTPUT (optional)

- Re-transmission : 4 to 20mA or 0 to 5V or 0 to 10V
- Update rate : 100msec.

ENVIRONMENTAL CONDITIONS

- Operating Range : 0°C to 50°C
- Storage Range : -20°C to 75°C
- Humidity : 85% max.

ISOLATION BREAKDOWN RATINGS

AC line with respect to all inputs and outputs : 2000 Volts. All other inputs and outputs with respect to relay contacts : 2000V AC

CONNECTION

Wire clamping screw terminals

WEIGHT

300 grams

SAFETY PRECAUTIONS

All safety related codifications ; symbols and instructions that appear in this operating manual or on the equipment must be strictly followed to ensure the safety of the operating personnel as well as the instrument.

If the equipment is not handled in a manner specified by the manufacturer it might impair the protection provided by the equipment.

CAUTION : Read complete instructions prior to installation and operation of the unit.

CAUTION : Risk of electric shock.

WIRING GUIDELINES

CAUTION :

1. To prevent the risk of electric shock power supply to the equipment must be kept OFF while doing the wiring arrangement.
2. Wiring shall be done strictly according to the terminal layout with shortest connections. Confirm that all connections are correct.
3. Use lugged terminals to meet M3 screws.
4. To eliminate electromagnetic interference use of short wire with adequate ratings and twists of the same in equal size shall be made.
5. Cable used for connection to power source, must have a cross section of 1mm² or greater. These wires shall have insulation capacity made of at least 1.5KV.

MAINTENANCE

1. The equipment should be cleaned regularly to avoid blockage of ventilating parts.
2. Clean the equipment with a clean soft cloth. Do not use Isopropyl alcohol or any other cleaning agent.

INSTALLATION GUIDELINES

CAUTION :

1. This equipment, being built-in-type, normally becomes a part of main control panel and in such case the terminals do not remain accessible to the end user after installation and internal wiring.
2. Conductors must not come in contact with the internal circuitry of the equipment or else it may lead to a safety hazard that may in turn endanger life or cause electrical shock to the operator.
3. Circuit breaker or mains switch must be installed between power source and supply terminals to facilitate power 'ON' or 'OFF' function. However this switch or breaker must be installed in a convenient position normally accessible to the operator.

CAUTION :

1. The equipment shall not be installed in environmental conditions other than those mentioned in this manual.
2. Fuse Protection : The equipment does not have a built in-type fuse. Installation of external fuse of rating 275V AC/1Amp for electrical circuitry is highly recommended.


3. Thermal dissipation of equipment is met through ventilation holes provided on chassis of equipment. Such ventilation holes shall not be obstructed else it can lead to a safety hazard.

4. The output terminals shall be strictly loaded to the manufacturer specified values/range.

MECHANICAL INSTALLATION

For installing the controller

1. Prepare the panel cutout with proper dimensions as shown



2. Remove clamp from the controller and push the controller into the panel cutout. Secure the controller in its place by pushing the clamp on rear side.
3. For proper sealing, tighten the screws evenly with required torque.


CAUTION :

The equipment in its installed state must not come in close proximity to any heating sources, caustic vapors, oils, steam, or other unwanted process by-products.

EMC Guidelines:


1. Use proper input power cables with shortest connections and twisted type.
2. Layout of connecting cables shall be away from any Internal EMI source.

TERMINAL CONNECTIONS



TERMINAL DESCRIPTION	TERMINAL
Live	L
Neutral	N
+ve mA	2
+ve V	3
+ve mV / TC / RTD1	4
- ve mV / TC- / RTD 2 / -ve mA / - ve V	5
+ve analog output	8
-ve analog output	9
NO for relay1	11
COM for relay1	12
NC for relay1	13
NO for relay2	14
COM for relay2	15
NC for relay2	16
GND / -ve sensor supply	17
+24 V / +ve sensor supply	18

FRONT PANEL DESCRIPTION




Functions	Key press
To enter or exit program mode	▲ + ♥ together for 3 seconds
To change levels	▲ or ♥ till Level is displayed. ■ + ▲ / ♥ to increase or decrease the level number.
To view function on the same level and to display the current option.	▲ or ♥ key once to view next / previous function.
To increase or decrease the value of a particular function.	■ + ▲ to increase and value of a particular function. ■ + ♥ to decrease the value of particular function.

NOTE : The unit will autoexit program mode after 60 seconds of inactivity.

To enter or exit program mode :
Press ▲ & ♥ together for 3 seconds

KEY PRESS	DISPLAY	DESCRIPTION
Press ▲ + ♥ for 3sec	LD	Lock code Enter valid lock code as set in the [LOC] parameter of level 0.

NOTE : Lock code will not be prompted if jumper J1 (besides the calibration jumper) is present.



PROGRAMMING OF LEVELS


PROGRAMMING OF LEVEL 0

KEY PRESS	DISPLAY	DESCRIPTION
Press ▲	[LUL]	
Press ■ + ♥	[LUL0]	Parameters in this level can be set.

Press ▲ key to select input sensor type

Default setting : J

Display	[INP]	for 1sec Input sensor selection
	[J]	J (-200 to 750°C)
Press ■ + ▲	[K]	K (-200 to 1350°C)
Press ■ + ▲	[T]	T (-200 to 400°C)
Press ■ + ▲	[R]	R (0 to 1750°C)
Press ■ + ▲	[S]	S (0 to 1750°C)
Press ■ + ▲	[P100]	PT100 (-100 to 850°C)
Press ■ + ▲	[mV]	mV (linear) -5 to 56mV
Press ■ + ▲	[10V]	10V DC
Press ■ + ▲	[20mA]	20mA DC



KEY PRESS	DISPLAY	DESCRIPTION
Press Δ key to select Temperature unit Default setting : °C NOTE : This parameter is not prompted if analog input is selected.		
Display	UNIT	for 1 sec.
	°C	Value displayed in °C
Press \square + Δ	°F	Value displayed in °F
Press Δ key to select Resolution Default value : 1 NOTE : This parameter is not prompted if input is R, S type thermocouple.		
Display	RESL	for 1 sec.
	1	Range : 1 / 0.1 for TC / RTD
Press \square + Δ	0.1	1 / 0.1 / 0.01 / 0.001 for AIN
Press Δ key to select Filter time constant Default value : 1sec.		
Display	FETC	for 1 sec.
Press \square + Δ / ∇	1	Range : OFF, 1 to 99 sec. to change value
Press Δ key to select PV bias Default value : 0.0		
Display	PIAS	for 1 sec.
Press \square + Δ / ∇	0.0	Range : -200 to 200 (fixed 0.1°C for TC/RTD) to change value
		For AIN display as per decimal point selected.

KEY PRESS	DISPLAY	DESCRIPTION
Press Δ key to select Display value scaling point1 Default value : 0 NOTE : This parameter is not prompted if TC/RTD input types are selected		
Display	DSCL	for 1sec
Press \square + Δ / ∇	0	Range : -1999 to DSCH For AIN display as per decimal point selected. to change value
Press Δ key to select input value scaling point 1 Default value : 0.00 NOTE : This parameter is not prompted if TC/RTD input types are selected		
Display	ISCL	for 1sec.
Press \square + Δ / ∇	0.00	Range : 0.0mA / -5mV / 0.0 V to ISCH (default value changes as per analog input selected) to change value
Press Δ key to select Display value scaling point 2 Default value : 9999 NOTE : This parameter is not prompted if TC/RTD input types are selected		
Display	DSCH	for 1sec.
Press \square + Δ / ∇	9999	Range : DSCL to 9999 For AIN display as per decimal point selected. to change value
Note : * mark explained in the user guide. AIN - Analog Input		

KEY PRESS	DISPLAY	DESCRIPTION
Press Δ key to select Input value scaling point 2 Default value : 20.0mA NOTE : This parameter is not prompted if TC/RTD input types are selected		
Input value scaling point high (ISCH) *		
Display	ISCH	for 1 sec.
Press \square + Δ / ∇	20.00	Range : ISCL to 20.00mA / 56mV / 10.00V (default value changes as per analog input selected) to change value
Press Δ key to select Reverse scaling Default setting : \square NO NOTE : This parameter is not prompted if TC/RTD input types are selected		
Reverse scaling*		
Display	RSCL	for 1 sec.
Press \square + Δ	YES	The display scaling point settings can be reversed by selecting Reverse scaling as YES
Press Δ key to select Set point high limit Default value : 750°C		
Set point high limit (SPHL)		
Display	SPHL	for 1sec
Press \square + Δ / ∇	750	Range : SPLL to max. range of sensor (for TC/RTD) SPLL to DPSH (for AIN) for AIN display as per decimal point selected. to change value
Press Δ key to select Set point low limit Default value : -200°C		
Set point low limit (SPLL)		
Display	SPLL	for 1sec
Press \square + Δ / ∇	-200	Range : min. range of sensor to SPHL (for TC/RTD) DSCL to SPHL (for AIN) for AIN display as per decimal point selected. to change value
Press Δ key to select Lock code Default setting : 0		
Lock code		
Display	LOCK	for 1sec
Press \square + Δ / ∇	0	Range : 0 to 9999 to change value
Press Δ key to select Reset Default setting : \square NO		
Reset		
Display	RESL	for 1sec
Press \square + Δ	YES	All parameters set to factory setting

NOTE : After altering the value of the input parameters press Δ or ∇ for change to actually take effect.

NOTE : Programming steps for Level1 (Alarm1 module) & Level2 (Alarm2 module) is same. Programming of level1 is shown.

PROGRAMMING OF LEVEL 1

Press \square + Δ till Level 1 is displayed


KEY PRESS	DISPLAY	DESCRIPTION
	LUL1	Parameters in this level can be set.
Press Δ key to select Alarm high limit Default value : 750°C NOTE : This parameter is not prompted if alarm mode is		
	HA	for 1sec
Press \square + Δ / ∇	750	Range : LA to SPHL (BAND mode) SPLL to SPHL (HA mode) for AIN display as per decimal point selected. to change value
Press Δ key to select Alarm low limit Default value : -200°C NOTE : This parameter is not prompted if alarm mode is		
	LA	for 1sec
Press \square + Δ / ∇	-200	Range : SPHL to HA (BAND mode) SPLL to SPHL (LA mode) for AIN display as per decimal point selected. to change value
Press Δ key to select Alarm hysteresis. Default value : 1.0 NOTE : This parameter is not prompted if alarm mode is		
	HYSL	for 1sec
Press \square + Δ / ∇	1.0	Range : 0.1 to 99.9 °C (for TC/RTD) 1 to 999 (for analog input) for AIN display as per decimal point selected. to change value

KEY PRESS	DISPLAY	DESCRIPTION
Press Δ key to select Alarm mode.		
	Default setting : <input type="text" value="HA"/>	
	In level 2 default setting is <input type="text" value="LA"/>	
Alarm mode *		
Display	<input type="text" value="nODE"/> for 1sec	
	<input type="text" value="OFF"/> Alarm off	
Press $\square + \Delta$	<input type="text" value="HA"/> High Alarm	
Press $\square + \Delta$	<input type="text" value="LA"/> Low Alarm	
Press $\square + \Delta$	<input type="text" value="bAND"/> Band Alarm	
Press $\square + \Delta$	<input type="text" value="FdA"/> Fault Diagnosis Alarm	
Press $\square + \Delta$	<input type="text" value="FOA"/> Fail Output Alarm	
Press Δ key to select Alarm latch status.		
	Default setting : <input type="text" value="OFF"/>	
NOTE : This parameter is not prompted when alarm mode is <input type="text" value="OFF"/>		
Latch alarm*		
Display	<input type="text" value="LECH"/> for 1 sec.	
Press $\square + \Delta$	<input type="text" value="OFF"/> When latch is ON Alarm status will be preserved at any process condition.	
	<input type="text" value="ON"/>	
Press Δ key to select Alarm hold status.		
	Default setting : <input type="text" value="OFF"/>	
NOTE : This parameter is not prompted if alarm mode is <input type="text" value="OFF"/>		
Hold Alarm*		
Display	<input type="text" value="HOLD"/> for 1 sec.	
Press $\square + \Delta$	<input type="text" value="OFF"/> Used to avoid alarm at power ON. Alarm is enabled only after the process value has reached the set point.	
	<input type="text" value="ON"/>	
Press Δ key to select Relay status for alarm1.		
	Default setting : <input type="text" value="EN"/>	
NOTE : This parameter is not prompted when alarm mode is <input type="text" value="OFF"/>		
Relay status for Alarm1		
Display	<input type="text" value="PLY"/> for 1 sec.	
Press $\square + \Delta$	<input type="text" value="EN"/> Relay Energized.	
	<input type="text" value="dEN"/> Relay De - energized	
Press Δ key to select Alarm annunciator.		
	Default setting : <input type="text" value="OFF"/>	
NOTE : This parameter is not prompted if alarm mode is <input type="text" value="OFF"/>		
Alarm annunciator*		
Display	<input type="text" value="ANN"/> for 1 sec.	
	<input type="text" value="OFF"/> <input type="text" value="OFF"/> No annunciator	
Press $\square + \Delta$	<input type="text" value="LED"/> <input type="text" value="LED"/> LED of alarm1 blinks at the rate of 0.2sec	
Press $\square + \Delta$	<input type="text" value="dSP"/> <input type="text" value="dSP"/> LED blinking ; display flashing b/w PV and message (ALRM) at 1 sec.	

NOTE : Applicable only if Analog output is available.

PROGRAMMING OF LEVEL 3		
Press $\square + \Delta$ till Level 3 is displayed		
KEY PRESS	DISPLAY	DESCRIPTION
	<input type="text" value="LUL3"/>	Parameters in this level can be set.
Press Δ key to select Manual.		
	Default setting : <input type="text" value="OFF"/>	
Manual		
Display	<input type="text" value="MANL"/> for 1sec	
	<input type="text" value="OFF"/> Used to set manual output On / Off.	
Press $\square + \Delta$	<input type="text" value="ON"/>	
Press Δ key to select Analog low scaling point		
	Default value : -9999	
NOTE : This parameter is prompted only if manual is <input type="text" value="OFF"/>		
Low scaling point		
Display	<input type="text" value="R-L0"/> for 1sec	
Press $\square + \Delta / \heartsuit$	<input type="text" value="9999"/> Programmable from -1999 to 9999.	
to change value		Fixed 1°C resolution for TC / RTD. For AIN display as per decimal point selected.
Press Δ key to select Analog high scaling point		
	Default value : 9999	
NOTE : This parameter is prompted only if manual is <input type="text" value="OFF"/>		
High scaling point		
Display	<input type="text" value="R-HI"/> for 1 sec.	
Press $\square + \Delta / \heartsuit$	<input type="text" value="9999"/> Programmable from -1999 to 9999	
to change value		Fixed 1°C resolution for TC / RTD. For AIN display as per decimal point selected.
Press Δ key to select Sensor error level		
	Default setting : <input type="text" value="HIGH"/>	
Sensor error level		
Display	<input type="text" value="SEPP"/> for 1 sec.	
Press $\square + \Delta$	<input type="text" value="HIGH"/> Incase of sensor failure the output can be set to high or low value of range.	
	<input type="text" value="LOW"/>	
Press Δ key to select Analog output %.		
	Default setting : <input type="text" value="00"/>	
NOTE : This parameter is prompted only if manual is <input type="text" value="ON"/>		
Analog output %		
Display	<input type="text" value="PERC"/> for 1 sec.	
Press $\square + \Delta / \heartsuit$	<input type="text" value="00"/> Programmable from 0.0 to 100.0	
to change value		

USER GUIDE	
ALARM MODES	
High Alarm:	
The alarm is turned ON when PV rises above a preset value.	
Low Alarm:	
The alarm is turned ON when PV falls below a preset value.	
Band Alarm:	
The alarm is turned ON when PV rises above or falls below a preset value.	
Fault Diagnosis Alarm:	
The alarm is turned ON in case a hardware failure occurs.	
Fail Output Alarm:	
The alarm is turned ON in case of : a) measurement value exceeds range b) Sensor reverse condition (applicable for TC/RTD).	
Latch Alarm:	
This function is used to latch the alarm. When activated, the alarm is latched until it is acknowledged manually, even though the alarm condition may have disappeared.	
Hold Alarm:	
When hold is selected, in any alarm mode, it prevents an alarm signal on power-up. The alarm is enabled only if the process temperature is within alarm range.	
Alarm display options :	
(1) Press the \square key to view the status of alarms	
(2) Press $\square + \Delta$ to view the status of next alarm (after alarm 2 it rolls over to alarm 1).	
Only the alarms that are active can be viewed.	
Alarm status (e.g : of alarm 1) will be displayed as follows: LA-1 for low alarm, HA-1 for high alarm, FO-1 for Fail output alarm, FD-1 for fault diagnosis.	
(3) Press $\square + \Delta$ to acknowledge the particular alarm (Alarm will be acknowledged only if latch ON).	
FILTER TIME CONSTANT :	
The filter is an adaptive digital filter that discriminates between measurement noise and actual process changes. If the signal is varying too greatly due to measurement noise, increase the filter value. If the fastest controller response is needed, decrease the filter value.	
BIAS :	
This value offsets the indicator's PV display value by the entered amount. This is useful in applications in which the sensor cannot provide the actual temperature signal due to mounting constraints, inaccuracy etc.	
SCALING FOR ANALOG INPUT :	
To scale the controller, two scaling points are necessary. Each scaling point has a coordinate pair of Display Values and Input Values. It is recommended that the two scaling points be at the low and high ends of the input signal being measured. Process value scaling will be linear between and continue past the entered points to the	



SETTING FOR MANUAL OUTPUT MODE :

KEY PRESS	DISPLAY	DESCRIPTION
Eg. For 4-20 mA if constant 12mA output current is desired then setting for manual output :		
Press $\square + \Delta$	<input type="text" value="LUL3"/>	
Press Δ	<input type="text" value="MANL"/> display momentarily	
Press $\square + \Delta / \heartsuit$	<input type="text" value="ON"/> (Selection for manual output mode)	
Press Δ	<input type="text" value="PERC"/>	
Press $\square + \Delta / \heartsuit$	<input type="text" value="50.0"/> Adjust the display to 50.0 to get 12mA at output	

SETTING FOR RETRANSMISSION MODE

Eg. : 1) For Temperature Input :
Input : RTD Input
Retransmission output : 4 - 20 mA
Desired output : 4mA at 0°C, 20mA at 400°C
Settings :

Press $\Delta + \heartsuit$	<input type="text" value="LUL1"/>	
Press $\square + \heartsuit$	<input type="text" value="LUL0"/>	
Press Δ	<input type="text" value="INP"/>	
Using $\square + \Delta / \heartsuit$	<input type="text" value="PI00"/> Select the Input type as RTD	
Press Δ till	<input type="text" value="LUL0"/> is displayed	
Press $\square + \Delta$ till	<input type="text" value="LUL3"/> is displayed	
Press Δ	<input type="text" value="MANL"/> display momentarily	
and then display	<input type="text" value="OFF"/> (Selection for retransmission mode)	
Press Δ	<input type="text" value="R-L0"/>	
Press $\square + \Delta / \heartsuit$	<input type="text" value="0"/> Adjust the display to 0	
Press Δ	<input type="text" value="R-HI"/>	


KEY PRESS	DISPLAY	DESCRIPTION
-----------	---------	-------------

Press $\square + \blacktriangle / \heartsuit$ 400 Adjust the display to 400
 Press \blacktriangle

Eg. : 2) For analog Input :
 Retransmission output : 4 - 20 mA
 Desired output : 4mA at 0V ; 20mA at 10V
 Input Scaling : 0V - 0 ; 10V - 400
 Settings :

Press $\blacktriangle + \heartsuit$ LUL!
 Press $\square + \heartsuit$ LUL0
 Press \blacktriangle INP
 Using $\square + \blacktriangle / \heartsuit$ UOLt Select the Input type as voltage
 Press \blacktriangle until d.S.C.L is displayed
 Using $\square + \blacktriangle / \heartsuit$ 0 Adjust the display to 0
 Press \blacktriangle I.S.C.L
 Press $\square + \blacktriangle / \heartsuit$ 0.00 Adjust the display to 0
 Press \blacktriangle d.S.C.H
 Press $\square + \blacktriangle / \heartsuit$ 400 Adjust the display to 400
 Press \blacktriangle I.S.C.H
 Press $\square + \blacktriangle / \heartsuit$ 10.0 Adjust the display to 10
Note : By default the display will be 10.00 for 0-10V Input
 Press \blacktriangle
 Setting for Retransmission :
 Press $\square + \blacktriangle$ till LUL3
 Press \blacktriangle RRRL displays momentarily
 and then display OFF
R-L0
 Press $\square + \blacktriangle / \heartsuit$ 0 Adjust the display to 0
R-H1
 Press $\square + \blacktriangle / \heartsuit$ 400 Adjust the display to 400
 Press \blacktriangle

CONNECTION WITH 2-WIRE TRANSMITTER



CALIBRATION CERTIFICATE

Date: _____
 Model No: _____
 Sr. No.: _____

Claimed Accuracy : ± 0.25 % of full scale ± 1 digit
 (After 20min warmup time)



The calibration of this unit has been verified at the following values :

SENSOR	CALIBRATION TEMP. (°C) (0.1Resolution)	DISPLAY VALUE (°C)
K	35.0	35.0
	700.0	700.0
	1350	1350
PT100	0.0	0.0
	500.0	500.0
	800.0	800.0

SENSOR	CALIBRATION VALUE (0.1Resolution)	DISPLAY VALUE
Voltage (VDC)	0.0	0.0
	10.0	10.0
Current (mA)	0.0	0.0
	20.0	20.0

The thermocouple / RTD curves are linearised in this microprocessor based product; and hence the values interpolated between the readings shown above are also equally accurate; at every point in the curve.

Unit is accepted as accuracy is within the specified limit of claimed accuracy and certificate is valid up to one year from the date of issue

CHECKED BY :

(Specifications subject to change as development is a continuous process.)

Selec Controls Pvt. Ltd., India
Factory Address :
 EL-27/1, Electronic Zone, TTC Industrial Area,
 MIDC, Mahape, Navi Mumbai - 400 710, INDIA.
 Tel. No. : +91-22-28476443 / 1882
 Fax No. : +91-22-28471733 | Toll free : 1800 227 353
 Website: www.selec.com | Email: sales@selec.com

Disclaimer : *This product is strictly for industrial use and for sale in non European countries only*