



PINZE PER CIRCUITO STAMPATO

PCB Fuses Clips | *Pinces pour circuit imprimé*


PZ1001	Per fusibili 5x20	For 5x20 fuses	Pour fusibles 5x20
	Corrente 10 A	Current 10 A	Courant 10 A
	Contatti Bronzo stagnato	Contacts Tinned bronze	Contacts Bronze étamé
	Diametro 5 mm	Diameter 5 mm	Diamètre 5 mm
	 1000 pz 1000 pcs 1000 pces		 pronta in stock en stock



PZ1009	Per fusibili 5x20	For 5x20 fuses	Pour fusibles 5x20
	Corrente 15 A	Current 15 A	Courant 15 A
	Contatti Bronzo fosforoso stagnato	Contacts Tinned phosphorous bronze	Contacts Bronze phosphoreux étamé
	Diametro 5 mm	Diameter 5 mm	Diamètre 5 mm
	 1000 pz 1000 pcs 1000 pces		 pronta in stock en stock



PZ1003	Per fusibili 5x20	For 5x20 fuses	Pour fusibles 5x20
	Corrente 10 A	Current 10 A	Courant 10 A
	Contatti Bronzo fosforoso stagnato	Contacts Tinned phosphorous bronze	Contacts Bronze phosphoreux étamé
	Diametro 5 mm	Diameter 5 mm	Diamètre 5 mm
	 1000 pz 1000 pcs 1000 pces		 pronta in stock en stock



Foro da praticare sul circuito stampato = Ø 1,5 mm
 PCB hole = Ø 1,5 mm
 Perçage à faire sur le circuit imprimé = Ø 1,5 mm

PZ1014	Per fusibili 5x20	For 5x20 fuses	Pour fusibles 5x20
	Corrente 15 A	Current 15 A	Courant 15 A
	Contatti Bronzo fosforoso stagnato	Contacts Tinned phosphorous bronze	Contacts Bronze phosphoreux étamé
	Diametro 5 mm	Diameter 5 mm	Diamètre 5 mm
	 1000 pz 1000 pcs 1000 pces		 pronta in stock en stock

